DEPARTMENT OF TRANSPO FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

January 1	995
-----------	-----

DATE

February 13,1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

Federal Railroad Admin. Suite 440, North Tower 1720 Peachtree Rd., NW Atlanta, GA. 30309

REPORTING CARRIER (railroad & region or division)

Norfolk Southern Corporation

Division - Virginia

REPORTING OFFICER (signature/title)

General Manager - S&E

Communications & Signal Dept.

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a faise proceed causing corresponding indications of a cah signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic AB-Automatic block ACS-Automatic cab signal

APB-Absolute permissive block MB-Manual block ATC-Automatic train control

ATS-Automatic train stop CL-Color light CPL-Color position light

E-Electric

EM-Electromechanical EP-Electropneumatic FP-False proceed M-Mechanical P-Pneumatic PL-Position light

SA-Semiautomatic TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
BLOCK SYSTEMS X AB APB TC	01/29/95	8575	track circuit	Ford, VA
INTERLOCKING MATIC				
REMOTE MANUAL				
ATS ATC ACS				
⁴ OTHER (specily)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

, had lead unit 8575 fail with a wheel slip alarm. The train was Train No. 235, Engineer . Conductor stopped and the rest of the units were used to move the train to the adjacent track. Mechanical shop employees then attempted to move the stalled engine which was by that time alone in the block. The protecting signal was being observed by Trainmaster and the crew of No. 235, and they noticed that it was flopping between a stop and a clear indication while the attempt was being made to move the engine.

Signal personnel were called to investigate, and by the time they arrived, engine 8575 had been moved into a spur track. It was found that the track relay, a 2 ohm, 4 point, DN11, could be shunted with a 0.06 ohm shunt at either end and at the point where the engine was being operated at the time the false clear was observed. The track relay was tested and was found to be in spec. The Mechanical forces were questioned about the operation and condition of engine 8575, and they said that it had been leaking grease profusely to the rail. Due to this grease and the icy conditions, they had operated the sanders while attempting to move the engine. The condition was duplicated as closely as possible with an engine heavily sanding the rail and loss of shunt did occur. The cause was determined to be the grease/sand combination on the rails that resulted in the intermittent loss of shunt.

Once the rails were determined to be sufficiently clean of the grease, the signals were fully returned to service.