

DEPARTMENT OF TRANSPORTATION  
**FEDERAL RAILROAD ADMINISTRATION**  
**FALSE PROCEED SIGNAL REPORT**

REPORT FOR (month/year)  
 January 1995

DATE  
 February 3, 1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

REPORTING CARRIER (railroad & region or division)  
 Union Pacific Railroad  
 1416 Dodge Street  
 Omaha, Nebraska  
 Council Bluffs Service Unit

MAIL TO  
 Director of Railroad Safety  
 Federal Railroad Administration  
 Room 1807  
 911 Walnut Street  
 Kansas City, MO 64106-2009

REPORTING OFFICER (signature/title)  
 \_\_\_\_\_  
 Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

- A = Automatic
- AB = Automatic block
- ACS = Automatic Cab Signal
- APB = Absolute permissive block
- ATC = Automatic train control
- ATS = Automatic train stop
- CL = Color light
- CPL = Color position light
- E = Electric
- EM = Electromechanical
- EP = Electropneumatic
- FP = False proceed
- MB = Manual block
- M = Mechanical
- P = Pneumatic
- PL = Position light
- SA = Semiautomatic
- TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	1/20/95	NLNP-18	None	Darr, Nebraska
2 INTERLOCKING <input type="checkbox"/> AUTOMATIC <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (Specify)				

**NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN**

On January 20, 1995, at 15:53 (CDT) westbound NLNP-18 on the Council Bluffs Subdivision was stopped on Track 1 at Control Point B233 with westbound LND-15 occupying Track 1 west of the control point. NLNP-18 reported signal 1W west from red to green about four times in 5-second durations.

An investigation could not duplicate the occurrence, and it was determined that loss of shunt by LND-15, a single 4-axle locomotive, had caused the signal display.

All applicable tests were performed.

*John T. Gitting*  
 JAM  
 FP 95-6-1

(If more space is required, continue on reverse)