DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Pirector of Railroad Safety
Federal Railroad Administration
Room 1807
911 Walnut Street
Kansas City, MO 64106-2009

REPORT FOR (month/year)

June 1995

DATE

June 29, 1995

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

San Antonio Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals
The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic
AB = Automatic block
ACS = Automatic Cab Signal

APB = Absolute permissive block ATC = Automatic train control ATS = Automatic train stop

CL = Color light
CPL = Color position light
E = Flectric

EM = Electromechanical

EP = Electropneumatic FP = False proceed

MB = Manual block
M = Mechanical

P -= Pneumatic
PL = Position light

SA = Semiautomatic TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
BLOCK SYSTEMS MAB APB TC	6-16-95	UP6317	Switch Circuit Controller	Stanton, Texas
2 INTERLOCKING				
AUTOMATIC SYSTEMS ATS ATC ACS				
4 OTHER (Specify)	-			
NATURE AND CAUSE OF FAILURE/CORREC	TIVE ACTION	TAKEN	L	<u> </u>

On I and 1005 and 55 (ODE)

On June 16, 1995, at 10:55 (CDT) westbound FWEP16 on the Baird Subdivision reported a green westbound signal at the east end of Stanton with the switch reverse at the west end of Stanton.

An investigation revealed the switch circuit controller at the west end of Stanton had bad roller and tension springs that, under vibration, would lose the "shunt circuit" with the switch in a reverse position.

The signal system was restored to proper operation, and all applicable tests were performed.

1.2