DEDARTMENT	T OF TO ANGR	OPTATION		1				
DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION								
FALSE PROCEED SIGNAL REPORT				DATE	05-27-96			
MAIL TO				REPORTING CARRIER (railroad & region or division)				
Mr. Tom McFarlin Signal & Train Control Specialist Federal Railroad Administration 1100 Main Street, Suite 1130 Kansas City, MO 64105				BURLINGTON NORTHERN SANTA FE RAILROAD KANSAS DIVISION				
		FEDE △○	ERAL	PALL!	ROAN -			
				REPORTING OFFICER (signature/title)				
'96 MAY 3				31 A	AVP Signal 3:52			
A failure should not be counted more than one time in the 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System				The following abbreviations may be used in the report A -Automatic AB -Automatic block ACS -Automatic cab signal APB -Absolute permissive block ATC -Automatic train control ATS -Automatic train stop CL -Color light			EM EP FP	Electromechanical -Electropneumatic -False proceed
A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.							MP	-Manual block
							M P	-Mechanical
							P PL	-Pneumatic -Position light
				CPL- Color position light			SA	-Semiautomatic
				E -Electric			TC	-Traffic Control
				_		-		
TYPE OF SYSTEM				LOCOM	OTIVE OR TRAIN	DEVICE THAT FAILED	LOCATION (City and State)	
1 BLOCK SYSTEMS AB AB	STEMS X TC		5-21-96		TRAIN 1-121-20 COLOR LIGHT SIGNAL		SOUTH ELWOOD MO	
2 INTERLOCKING		AUTO	<u> </u>					
		MATIC						
3 AUTOMATIC SYSTEMS		•					1	
. ATS AT	rc	ACS						
4 OTHER (specify)								
			L					
NATURE AND CAUSE OF FA	AILURE/CORR	ECTIVE ACTI	ON TAKE	N				

At approximately 0930 Hrs train 120 (Southbound holding main) reported that while making a meet with train 121 (Northbound entering siding) at South Elwood that Signal 14LB South bound signal on siding was Lunar. Signal 14LB lower unit had been shot with a small caliber rifle breaking inner RED lens giving the appearance of a lunar signal. Replaced outer and inner lens color test performed all OK. Time reported OK at 1100 HRS.
If more space is required continue on reverse)