

DEPARTMENT OF TRANSPORTATION
 FEDERAL RAILROAD ADMINISTRATION
FALSE PROCEED SIGNAL REPORT

DATE December 22, 1997

MAIL TO
 Mr. Tom McFarlin
 Signal & Train Control Specialist
 Federal Railroad Administration
 1100 Main Street, Suite 1130
 Kansas City, MO 64105

REPORTING CARRIER (railroad & region or division)
 Burlington Northern Santa Fe Railway
 Northern Lines
 Powder River Division
 Butte Subdivision
 REPORTING OFFICER (signature/title)
 Assistant Vice President Signal

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System

A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.

- The following abbreviations may be used in the report
- A -Automatic
 - AB -Automatic block
 - ACS -Automatic cab signal
 - APB -Absolute permissive block
 - ATC -Automatic train control
 - ATS -Automatic train stop
 - CL -Color light
 - CPL- Color position light
 - E -Electric
 - EM Electromechanical
 - EP -Electropneumatic
 - FP -False proceed
 - MP -Manual block
 - M -Mechanical
 - P -Pneumatic
 - PL -Position light
 - SA -Semiautomatic
 - TC -Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE OR TRAIN NUMBER	DEVICE THAT FAILED	LOCATION (City and State)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	12/17/97	EMD 9068	none	Crawford, Nebraska
2 INTERLOCKING <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> AUTO <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Approximately 1545 MST EMD 9068 with 115 loads 0 empties, 15600 tons, 6700 feet long, train symbol CBKMSLC459, Engineer Conductor was eastbound Main Track 2 and had a green/red at Control point Crossover 437.5, flashing yellow/red at intermediate signal 2-427.2 and red/red at control point Crossover 425.5. Engineer made normal train stop in approach of red/red at Crossover 425.5 and was advised by Signal Inspector and Signal Electronic Technician that they were troubleshooting a signal problem and that they had caused intermediate signal 2-427.2 to display flashing yellow/red. Crew notified dispatcher, and Signal Supervisor was notified. Signal Supervisor obtained statements form Inspector and Electronic Technician. Inspector was testing for a cross between the B12 and EC-B12 battery, dispatcher had given him permission to have control point Crossover 425.5 in local control. Inspector was attempting to isolate the cross by opening wires one at a time off of the C12 buss and had removed the C12 coil wire from the buss which fed the 2EAHGR relay. Removing the wire created a pickup path that passed through the coils of the 2EASPR, the 2EAHGR to the 2EAHGPR by way of a parallel coil wire connection and energized the 2EAHGPR causing the Electrocode unit to transmit a flashing yellow code 4 to signal 2-427.2.

Corrective action: Parallel coil wire connection between the 2EAHGR and 2EAHGPR was separated and the 2EAHGPR was made a repeater of the 2EAHGR. Signal system tested with no exceptions. Investigation scheduled to determine responsibilities of Inspector and Electronic Technician.