## DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

 REPORT FOR (month/year)

December 1997

DATE

December 16, 1997

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

St. Louis Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

KANSAS CHY III

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report:

A = Automatic EM = Electrome

AB = Automatic block ACS = Automatic Cab Signal

APB = Absolute permissive block ATC = Automatic train control

ATS = Automatic train stop CL = Color light

CPL = Color position light E = Electric EM = Electromechanical EP = Electropneumatic

FP = False proceed
MB = Manual block
M = Mechanical

P == Pneumatic
PL = Position light
SA = Semiautomatic
TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS  DAB DAPB TC	12/11/97	UP 3539	None	Pace, MO
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL				
3 AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS				
4 OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On December 11, 1997, at 09:25 CST, on the Sedalia Subdivision, at Page, Missouri, eastbound MKCAS-09, observed the eastbound approach signal on track #1, at milepost 59.0 indicating a yellow over yellow signal, with the eastbound home signal on track #1, at CP M058 indicating a red signal.

An investigation revealed the eastbound approach signal at milepost 59.0 had a bottom signal head that has one light which is yellow. The access door to the bottom signal head was open and sunlight shining into the back of it gave the appearance of a yellow signal on the bottom head.

The signal system was restored to proper operation, and all applicable tests were performed.