

Reg 4

T. Maske

GvH

3-18-98

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION

OMB No. 04-R-0028

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

March 1998

DATE

March 13, 1998

REPORTING CARRIER (railroad & region or division)

Norfolk Southern Corporation  
Division - Illinois

REPORTING OFFICER (signature/title)

Chief Engineer - Western Region  
Communications & Signal Dept.

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

Federal Railroad Administration  
16th Floor - Suite 16T20  
100 Alabama Street, SW  
Atlanta, GA 30303-3104

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A-Automatic
- AB-Automatic block
- ACS-Automatic cab signal
- APB-Absolute permissive block
- ATC-Automatic train control
- ATS-Automatic train stop
- CL-Color light
- CPL-Color position light
- E-Electric
- EM-Electromechanical
- EP-Electropneumatic
- FP-False proceed
- MB-Manual block
- M-Mechanical
- P-Pneumatic
- PL-Position light
- SA-Semiautomatic
- TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	3/10/98	UP 2961	poleline	Sidney, IL
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION  
RECEIVED

MAR 18 1998

ATLANTA, GEORGIA

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

At approximately 8:55 PM, westbound Train No. 71 with Engineer \_\_\_\_\_ and Conductor \_\_\_\_\_ reported the distant signal to East Sidney, 325.8, displayed **advance approach** and the East Sidney home signal displayed **stop**. The 325.8 signal should have displayed **approach** because East Sidney had not been lined for No. 71's move due to Train No. 409 working between the switches at Sidney.

Signal personnel called to investigate confirmed the **advance approach** aspect into a **stop**. This was caused by false energy on the 3258BH relay that controlled the bottom yellow. The false energy was the result of a line wrap between the 3258 BH wire and the 32695 TP wire at milepost D-327.1. Though the two line wires were tight and tied-in, we suspect the 50 MPH+ wind gusts on the previous day had blown something into the line resulting in the wrap. The wrap was removed, the signal system verified to be working as intended, and signals were returned to service at 12:45 AM, 3/11.

To keep this from recurring, the **advance approach** aspect has been eliminated on this signal. Instead of getting an **advance approach** when East Sidney is **approach**, signal 325.8 will repeat the yellow at East Sidney. This is a temporary fix since the poleline is to be eliminated and aspects will change in conjunction with a new NS/UP connecting track to be installed here in the near future.