## DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

DATE

January	: 1998

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

January 15, 1998

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

REPORTING CARRIER (railroad & region or division)

MAIL TO

Union Pacific Railroad 1416 Dodge Street Omaha. Nebraska

Director of Railroad Safety Federal Railroad Administration City Center Square, Suite 1130

Central Texas Service Unit

1100 Main Street

REPORTING OFFICER (signature/title)

Kansas City, MO 64105-2112 3 JAN 20 A 9:13

Chief Engineer-Signals The following abbreviations may be used in the report:

MANSAS COLL COL

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

EM = Electromechanical A - Automatic AB = Automatic block EP = Electropneumatic

 $\Lambda$  false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

ACS =: Automatic Cab Signal APB = Absolute permissive block ATC = Automatic train control ATS = Automatic train stop

FP = False proceed MB = Manual block M = Mechanical P -= Preumatic

CL = Color light CPL = Color position light E = Electric

PL = Position light SA = Semiautomatic TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS AB □ APB □ TC	1/10/98	UP 6060	AK card in Electrode unit	5 miles south of Odgen Jet., TX
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL				
AUTOMATIC SYSTEMS  DATS DATC DACS  4				
OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On January 10, 1998, at 06:00 CST, on the Austin Subdivision, south of Ogden Jct., Texas, northbound MLDLI 09, on track 2, observed northbound signal at Mile Pole 241.6 green with the next northbound signal at Mile Pole 238.4 red and the track north of Mile Pole 238.4 occupied.

An investigation revealed a defective 4K card in the Electrode unit at Mile Pole 241.6.

The signal system was restored to proper operation, and all applicable tests were performed.