## DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety Federal Railroad Administration City Center Square, Suite 1130 1100 Main Street Kansas City, MO 64105-2712 1997 - - - - - - - - 8.0\_ REPORTING CARRIER (railroad & region or division)

REPORT FOR (month/year)

DATE

April 1998

April 28, 1998

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

St. Louis Service Unit

REPORTING OFFICER (signature/title)

hief Engineer-Signals The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light

CPL = Color position light E = Electric

EM = Electromechanical

EP = Electropneumatic FP = False proceed

MB = Manual block

M = Mechanical

P -= Pneumatic PL = Position light

SA = Semiautomatic TC = Traffic Control

			L - Piccuic	Te Hame conde
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS  AB APB TC	4/23/98	UP 469W	None	Centertown, MO
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL				
3 AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS				
4 OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On April 23, 1998, at 10:10 CDT, on the Sedalia Subdivision, at Centertown, Missouri, westbound WPFLWB21, while stopped in the siding 200 yards east of control point M142, observed a yellow indication from the signal to leave the siding, with the switch lined normal.

An investigation revealed a phantom indication in the signal to leave the siding was caused by the sunlight washing out the red signal and making it appear yellow.

Shields were applied preventing the phantom signal, and all applicable tests were performed.