FEDERAL RAILROAD ADMINISTRATION FALSE PROCEED SIGNAL REPORT	June 2000
	July 5, 2000 REPORTING CARRIER
FP-00-2-5	Norfolk Southern Corporation Division: Pittsburgh
Mr. Michael Woods Federal Railroad Administration 16th Floor - Suite 16T20	REPORTING OFFICER
100 Alabama Street, SW Atlanta, GA 30303-3104	7-5-00 Chief Englaser - Northern Region
	Communications & Signal Department
TYPE OF SYSTEM DATE LOCOMOTIVE NUMBER	QEVICE THAT LOCATION (city and size)
	_ GEVICE THAT GOATION (chr and attack)
BLOCK SYSTEMS 8933, 2506 AB APB X TC 06/24/2000 8713 MITERLOCKING MATIC	_ DEVICE THAT LOCATION (city and state)

NATURE AND CAUSE OF FAILURE / CORRECTIVE ACTION TAKEN

At approximately 2:22 a.m., June 24, 2000, Train #62V, Engineer , Conductor was southbound at MP 10.5 on the Youngstown Line when they observed signal 10S displaying Approach Limited (yellow over flashing green) with signal at CP 13 Medium Approach (red over flashing yellow). The train crew knew that MP 10.5 should have been displaying yellow over solid green since they were lined to take the turnout at CP 13. The number 15 turnout at CP 13 is limited to 30 MPH, therefore, the signal observed by the train crew at 10S, yellow over flashing green, was improper since it was a 40 MPH speed limit through the turnout at CP 13.

Investigation determined that this improper signal was displayed due to our signal supervisor replacing the EC-4 box when it was in trouble on 6/1/00, at CP 13. He placed a control wire on the wrong terminal post of an EC-4 box which generated a Code 4 instead of a Code 3. He failed to make proper in-service tests after disarrangement of the signal system.

The wiring on the EC-4 box was corrected, in-service tests were done and signal system placed back in service 6/24/00.

