## DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no

talse proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad

REPORT FOR (month/year)

April 2001

FP 2001-5-4

DATE

April 16, 2001

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

Kansas City Service Unit

REPORTING OFFICER (signature/title)

01 APR 20 pt 2/21

The following abbreviations may be used in the report:

Chief Engineer-Signals

EM = Electromechanical

EP = Electropneumatic

FP = False proceed

MB = Manual block

TC = Traffic Control

A failure should not be counted more than one time in items 1, 2/3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic
AB = Automatic block
ACS = Automatic Cab Signal
APB = Absolute permissive block
ATC = Automatic train control
ATS = Automatic train stop
CL = Color light

E = Electric

ATC = Automatic train control
ATS = Automatic train stop
CL = Color light
CPL = Color position light

ATC = Automatic train control
M = Mechanical
P -= Pneumatic
PL = Position light
SA = Semiautomatic

LOCOMOTIVE **DEVICE THAT** TYPE OF SYSTEM DATE LOCATION(city and state) NUMBER **FAILED BLOCK SYSTEMS** Wagoner, OK 4/11/01 **BNSF9788** NONE □тс □ AB □ APB INTERLOCKING □ AUTOMATIC MANUAL □ REMOTE **AUTOMATIC SYSTEMS** ☐ ACS □ ATS ☐ ATC OTHER (Specify)

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On April 11, 2001, at 16:30 CDT, at Wagoner, OK, on the Cherokee Subdivision, southbound, CGDRO 10, on the main track, at MP 486.3, reported the southbound approach signal to the Wagoner Interlocker displayed an approach diverging (yellow over yellow) into a red southbound home signal.

An investigation revealed that lightning had melted two wires together, which applied voltage to the bottom aspect of the southbound approach signal.

The signal system was restored to proper operation, and all applicable tests were performed.

the end of the month.

MAIL TO

Administration, Office of Safety, Washington, D.C. 20590.

Director of Railroad Safety

Kansas City, MO 64106

901 Locust Street

Federal Railroad Administration