

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINSTRATION

FALSE PROCEED SIGNAL REPORT

All Railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Admininstration within five days after a false proceed occurs. If no false proceed occurs during any calender month, a report showing "No Fallures" must be filed within ten days after the

Copies of this form will be furnished upon request to the Department of Transportation, Federal Reliroed Admininstration, Office of Safety, Washington, D.C. 20590

REPORT FOR (month/year) 10/11/2002

REPORTING CARRIER (railroad and region or division)

CSX Transportation Train Control

MAIL TO

Federal Railroad Admin. 61 Forsyth St SW Suite 16T20 30303 Atlanta, Ga.

REPORTING CARRIER (signature/little-

Director Signal Reliability

A failure should not be counted more than one time in items 1, 2, 3, and 4; the fa A ratture should not be counted more than one time in terms 1, 2, 3, and 4, the table should be classified under the basic system or appliance of which it forms accessful part, E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

AB-Automatic block ACS-Automatic cab signal APB-Absolute permissive block ATC-Automatic train control ATS-Automatic train stop CL-Color light CPL-Color position light E-Electric

EM-Electromechanical EP-Electropneumatic MB-Manual M.Mechanical P-Pneumatic Pt -Position light SA-Semiautomatic TC-Traffic control

/ TYPE OF SYSTEM DATE		LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
BLOCK SYSTEMS	10/11/2002	Q416-09	S8PT Connectors	W.E. Space Center Lordstown , OH
AB APB X TC			ļ	
2 INTERLOCKING AUT	·O-			
REMOTE MAI	NUAL			
3 AUTOMATIC SYSTEMS				
ATS ATC AC	s		 	
4 OTHE (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On October 11, 2002 at 6:00 AM the Q416-09 approached Intermediate Signal W90.41, displaying a clear signal and stopped east of the signal, made a cut on Q416-09, to pick up cars at the West end Space Center, Goodman Yard. The train crew went west of Intermediate Signal W90.41 and observed that the signal indication changed to restricted proceed. The crew went west of the trailing point switch, threw the switch reverse and entered the west end Space Center. The switch was left open while working and upon clearing the fouling circuit, train crew reported that the W90.41 signal indicated clear. When the train crew came back out onto the fouling circuit, W90.41 signal indicated restricted proceed. The train crew tied back onto their train, restored the switch normal and proceeded west with permission. Signals were removed from service and signal personnel dispatched to the site. Investigation revealed that corroded track connections to the rail were the cause of the false proceed signal. All track connections from the circuit controller to the rail were renewed and a new switch circuit controller installed. Full operational tests were performed and the signals were restored to service.