DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety Federal Railroad Administration 901 Locust Street Kansas City, MO 64106

REPORT FOR (month/year)

November, 2002

DATE

December 04, 2002

REPORTING CARRIER (railroad & region or division

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Roseville Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block ACS = Automatic Cab Signal APB = Absolute permissive

block

ATC = Automatic train control

ATS = Automatic train stop

E - Electric

CL = Color light CPL = Color position light EM = Electromechan:

EP = Electropneumati FP = False proceed

MB = Manual block

M = Mcchanical P -= Pneumatic

PL = Position light SA = Semiautomatic

TC = Traffic Control

| | E = Electric | | | |
|---|--------------|----------------------|--------------------|--------------------------|
| TYPE OF SYSTEM | DATE | LOCOMOTIVE NUMBER | DEVICE THAT FAILED | LOCATION(city and state) |
| 1. BLOCK SYSTEMS □ AB □ APB X TC | 11/29/02 | UP 6573 | NONE | Wellington, UT |
| 2 INTERLOCKING AUTOMATIC PREMOTE MANUAL | | | | |
| 3 AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS | | | | |
| 4 OTHER (Specify) | | ДВЕСІОИ | TID SASNAN | |

65: Zd 6- 330 ZO.

On November 29, 2002, at 10:02 MST, in Wellington, UT, on the Green River Subdivision, eastbound CCSWE-25, on the main track, at mile post 613.50, reported that the eastbound signal at West Wellington cycled from flashing yellow to green with a westbound train entering the siding at East Wash. FEDERAL RAILROAD

An investigation revealed that the point detector on the power switch a East Wash was failing intermittently as the westbound train passed over the reverse switch, causing the main track HD line circuit feeding west to pump. The existing circuitry at West Wash/East Wellington pole changed the HD circuit feeding west in response to this pumping action, resulting in a green aspect at West Wellington.

The circuits at west Wash/East Wellington were revised to prevent a reoccurrence of this failure. All applicable tests were performed.

Mades & Josef 12-9-02