

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION	DATE <input type="text" value="06-23-2003"/>
---	--

MAIL TO

Mr. James Drake  
Signal & Train Control Specialist  
Federal Railroad Administration  
901 Locust Street - Suite 464  
Kansas City, MO 64106

[james.drake@fra.dot.gov](mailto:james.drake@fra.dot.gov)

REPORTING CARRIER (railroad & region or division)  
Burlington Northern Santa Fe Railway

REPORTING OFFICER (signature/title)

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System

A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.

- The following abbreviations may be used in the report
- |                                |                       |
|--------------------------------|-----------------------|
| A -Automatic                   | EM -Electromechanical |
| AB -Automatic block            | EP -Electropneumatic  |
| ACS -Automatic cab signal      | FP -False proceed     |
| APB -Absolute permissive block | MP -Manual block      |
| ATC -Automatic train control   | M -Mechanical         |
| ATS -Automatic train stop      | P -Pneumatic          |
| CL -Color light                | PL -Position light    |
| CPL- Color position light      | SA -Semiautomatic     |
| E -Electric                    | TC -Traffic Control   |

TYPE OF SYSTEM	DATE	LOCOMOTIVE OR TRAIN NUMBER	DEVICE THAT FAILED	LOCATION (City and State)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	06-11-2003	ZWSPLAC408A	CABLE	SAN BERNARDINO, CA.
2 INTERLOCKING <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> AUTO MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

SIGNAL GANG REPLACED CABLE BETWEEN THE MAIN CONTROL HOUSE AND THE WEST BOUND CONTROL SIGNALS AT VERDEMONT. THE CONDUCTORS IN THE CABLE FOR THE CONTROL CIRCUIT OF BOTTOM HEAD ON THE # 1 MAIN TRACK WEST BOUND SIGNAL WERE HOOKED UP INCORECTLY, CAUSING A FALSE PROCEED SIGNAL.