

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)
8/28/2003

REPORTING CARRIER (railroad and region or division)

**CSX
Transportation
Train Control**

REPORTING CARRIER (signature/title)

Asst Chief Engineer - Signal Maint

Under the Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within ten days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.
Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

Federal Railroad Admin.
61 Forsyth St SW
Suite 16T20
Atlanta, Ga. 30303

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- | | |
|-------------------------------|----------------------|
| A-Automatic | EM-Electromechanical |
| AB-Automatic block | EP-Electropneumatic |
| ACS-Automatic cab signal | FP-False proceed |
| APB-Absolute permissive block | MB-Manual block |
| ATC-Automatic train control | M-Mechanical |
| ATS-Automatic train stop | P-Pneumatic |
| CL-Color light | PL-Position light |
| CPL-Color position light | SA-Semiautomatic |
| E-Electric | TC-Traffic control |

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	8/28/2003	N935-15	Wiring	East End of B & O Sid Fostoria, OH
2 INTERLOCKING <input type="checkbox"/> AUTO-MATIC <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On August 28th at approximately 21:10, westbound N93515 on #2 track at the East End of the B & O center siding, reported receiving a yellow over yellow (approach slow) into a stop signal at the West end of the B & O center siding. Signals were removed from service and signal personnel were dispatched. During testing and inspection of the signals, it was discovered that a wiring change from a prior project was made incorrectly that allowed the improper aspect to display if the R178WFSR stick relay was picked. The wiring error was corrected, operational tests were performed and the signals were returned to service.