DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
901 Locust Street
Kansas City, MO 64106

REPORT FOR (month/year)

April, 2003

DATE

April 28, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Salt Lake City

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light

CPL = Color position light

EM = Electromechanical EP = Electropneumatic

FP = False proceed

MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light SA = Semiautomatic

TC = Traffic Control

			E = Flecting	IC = Traffic Control
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
BLOCK SYSTEMS AB APB X TC	4/2303	UPY562	NONE	Salt Lake City, UT
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL		KANS	FEDEI ADK	
3 AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS		AS CIT	RAL FINES	
4 OTHER (Specify)		Y REG	AIL 5	
NATURE AND CAUSE OF FAILURE/CORREC	TIVE ACTION TAKE	N S	<u> </u>	
 -		₫		

On April 23, 2003, at 10:25 CDT, in Salt Lake City, UT, on the Lynndyl Subdivision, westbound YSC44 22, at mile post 782.40, reported the westbound signal on No. 1 track was red over lunar without the signal being requested from the dispatcher.

An investigation revealed the sun reflecting off the outer lens of the bottom red aspect gave the appearance of a lunar

The outer lens was replaced, and all applicable tests were performed.