DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

the end of the month.

Director of Railroad Safety
Federal Railroad Administration
901 Locust Street
Kansas City, MO 64106

REPORT FOR (month/year)

May, 2003

DATE

May 21, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Salt Lake City Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light CPL = Color position light EM = Electromechanical EP = Electropneumatic

FP = False proceed

MB = Manual block

M = Mechanical
P = Pneumatic

PL = Position light

SA = Semiautomatic

E = Electric TC = Traffic Control LOCOMOTIVE **DEVICE THAT** NUMBER **FAILED** LOCATION(city and state) TYPE OF SYSTEM DATE **BLOCK SYSTEMS** H2 Wells, NV 5/03/03 **UP 4580** ☐ APB TC. **X** AB mechanism INTERLOCKING □ AUTOMATIC ☐ REMOTE ■ MANUAL **AUTOMATIC SYSTEMS** ☐ ATC ☐ ACS ☐ ATS OTHER (Specify)

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On May 10, 2003, at 14:40 CDT, in Wells, NV, on the Lakeside Subdivision, eastbound 1ZLTG1 10, on the #2 Track, at mile post 605.2, reported the eastbound signal at MP 605.2 displayed a green aspect with the next block east occupied.

An investigation revealed the H2 mechanism at the eastbound signal at MP 605.2 was stuck displaying a green aspect.

The H2 mechanism was replaced and all applicable tests were performed.

(If more space is required, continue on reverse)

FORM FRA F 6180-14 (6-72)