DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
901 Locust Street
Kansas City, MO 64106

REPORT FOR (month/year)

November, 2003

DATE

November 18, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Los Angeles Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g., assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light

CPL = Color position light
E = Electric

EM = Electromechanical

EP = Electropneumatic

FP = False proceed MB = Manual block

M = Mechanical

P == Pneumatic

PL = Position light

SA = Semiautomatic

TC = Traffic Control

TYPE OF SYSTEM		DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
BLOCK SYSTEMS AB APB	X TC	11/15/03	UP 3934	case wiring	Niland, CA
2 INTERLOCKING □ REMOTE	☐ AUTOMATIC ☐ MANUAL				
AUTOMATIC SYSTEMS ATS ATC	ACS				
4 OTHER (Specify)					

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On November 15, 2003, at 22:14 PST, in Niland, CA, on the Yuma Subdivision, eastbound MWCFW-13, on the main track, at MP 665.63, reported the eastbound absolute signal at CPSP665 (West Niland) was yellow over dark for a move into the siding.

An investigation revealed the 84RAHPR relay energized.

case wiring had deteriorated, which allowed false battery to keep

The wire was replaced, and all applicable tests were performed.

(If more space is required, continue on reverse)

GPO 929-92