

**FALSE PROCEED SIGNAL REPORT**

All Railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month. Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C.

MAIL TO

Federal Railroad Admin.  
61 Forsythe St SW  
Suite 16T20  
Atlanta, Ga. 30303

REPORT FOR (month/year)

REPORTING CARRIER (railroad and region or division)

**CSX  
Transportation  
Train Control**

REPORTING CARRIER (signature/title)

*GENERAL MANAGER SIGNAL MISC*

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g., assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or

The following abbreviations may be used in the report

- A-Automatic
- AB-Automatic block
- ACS-Automatic cab signal
- APB-Absolute permissive block
- ATC-Automatic train control
- ATS-Automatic train stop
- CL-Color light
- CPL-Color position light
- E-Electric
- EM-Electromechanical
- EP-Electropneumatic
- FP-False proceed
- MB-Manual block
- M-Mechanical
- P-Pneumatic
- PL-Position light
- SA-Semiautomatic
- TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
<b>BLOCK SYSTEMS</b> <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	6/22/98	Q50321	None	NE Weston Weston, OH
<b>INTERLOCKING</b> <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
<b>AUTOMATIC SYSTEMS</b> <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On June 22, 1998, the southbound Q50321 reported a clear signal at the NE Weston and a stop signal at the SE Weston. The signals were removed from service and signal personnel dispatched to investigate. The situation was simulated by the signal personnel and the false clear was confirmed. The investigation identified that reverse polarity on a pair of HD wires had caused the false clear signal. The polarity of the HD wires was corrected and the signal system was tested and returned to service.

A signal maintainer was called to investigate a problem at the SE Weston on June 14. The maintainer identified the problem as an open in the HD lines and changed to a pair of spare wires. He placed two spare wires on each of the open cable wires marked R22HD4 and NR22HD1. He then went to Taylor St. crossing warning system and jumpered the wires together to complete the circuit from the SE Weston. The maintainer checked voltage to verify the circuit but failed to perform an adequate operational test of the circuit before returning the signals to service. The polarity of the circuit was inadvertently swapped by the maintainer. This was determined to be the cause of the false clear.

