

FP-10-107

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)
April, 1995

DATE
4/19/95

REPORTING CARRIER (railroad & region or division)

CONSOLIDATED RAIL CORPORATION

Pittsburgh

REPORTING OFFICER (signature/title)

Chief Engineer-C&S

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

R. C. Murray
Supervisory Railroad Safety Specialist
Federal Railroad Administration
Scott Plaza Two
Suite 550
Philadelphia, PA 19113

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A—Automatic	EM—Electromechanical
AB—Automatic block	EP—Electropneumatic
ACS—Automatic cab signal	FP—False proceed
APB—Absolute permissive block	MB—Manual block
ATC—Automatic train control	M—Mechanical
ATS—Automatic train stop	P—Pneumatic
CL—Color light	PL—Position light
CPL—Color position light	SA—Semiautomatic
E—Electric	TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	4/18/95	Train UCI-18A Engine #101	Signal 29.2	Shire Oaks, PA
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Engineer on Train UCI-18A reported Automatic Signal 29.2 displayed a clear Aspect with 2S at CP Oak displaying Dark over Red. Problem was determined to be incorrect circuit design of the 292TATN and 292TATB track circuit selection through the 2S ALOR. Circuitry was corrected and signal system tested and restored to service. Investigation being conducted to determine responsibility.

RECEIVED
DEPARTMENT OF TRANSPORTATION
APR 21 1995