

DEPARTMENT OF TRANSPORTATION
 FEDERAL RAILROAD ADMINISTRATION
**ALLEGED
 FALSE PROCEED SIGNAL REPORT**

REPORT FOR (month/year)
 May 1995

DATE May 8, 1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.
 Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad & region or division)
 Southern Pacific
 Transportation Co.
 Denver Division
 Subdivision 1-A

MAIL TO
 Director of Railroad Safety
 Region 7
 Federal Railroad Administration
 650 Capital Mall, Suite 7707
 Sacramento, CA 95814

REPORTING OFFICER (signature/title)
 Engineer - Signals

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.
 A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.
 A—Automatic
 AB—Automatic block
 ACS—Automatic cab signal
 APB—Absolute permissive block
 ATC—Automatic train control
 ATS—Automatic train stop
 CL—Color light
 CPL—Color position light
 E—Electric
 EM—Electromechanical
 EP—Electropneumatic
 FP—False proceed
 MB—Manual block
 M—Mechanical
 P—Pneumatic
 PL—Position light
 SA—Semiautomatic
 TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	5-1-95	1DWHLE 01	Signal 619	Frazer, CO.
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL <input type="checkbox"/> AUTO-MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN
 On May 1, 1995 at approximately 7:40 PM, Engineer _____ operating train No. 1DWHLE 01 traveling West, reported that Signal 619 at East End of Frazer was CLEAR, then suddenly went RED/RED in their face.
 Under the direction of Signal Supervisor _____, the signal system was removed from service and thoroughly tested. All tests showed the signal system to be working as intended with no exceptions. In addition, computer room reviewed tapes and found no control sent to that location or no indication of CLEAR signal from East Frazer.
 The signal system system was restored to service on May 1, 1995 at 11:59 PM.