

DEPARTMENT OF TRANSPORTATION
 FEDERAL RAILROAD ADMINISTRATION
ALLEGED
FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

July, 1995

DATE July 31, 1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad & region or division)

Southern Pacific
 Transportation Co.
 El Paso Division
 Valentine Subdivision

MAIL TO

Director of Railroad Safety
 Region 7
 Federal Railroad Administration
 650 Capital Mall, Suite 7707
 Sacramento, CA 95814

REPORTING OFFICER (signature/title)

Engineer - Signals

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A—Automatic
- AB—Automatic block
- ACS—Automatic cab signal
- APB—Absolute permissive block
- ATC—Automatic train control
- ATS—Automatic train stop
- CL—Color light
- CPL—Color position light
- E—Electric
- EM—Electromechanical
- EP—Electropneumatic
- FP—False proceed
- MB—Manual block
- M—Mechanical
- P—Pneumatic
- PL—Position light
- SA—Semiautomatic
- TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	7-25-95	SP 1LBMFT-24	Signal FM	West Rosenfeld, TX.
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On July 25, 1995 at approximately 6:45 PM, Engineer _____ operating train No. 1LBMFT-24 traveling East, reported that the Approach Signal to the West End of Rosenfeld was FLASHING YELLOW, that Signal FM at the West End was GREEN and that the next signal, the TM Signal at the East End of Rosenfeld was RED. The FM signal at the West End should have been YELLOW.

Under the direction of Signal Supervisor _____, the signal system was placed at stop and thoroughly tested. All test showed the signal system to be working as intended with no exceptions.

The signal system was returned to service on July 26, 1995 at 10:00 AM.