

FP 2-16

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

August

DATE

August 8, 1995

REPORTING CARRIER (railroad & region or division)

CONSOLIDATED RAIL CORPORATION

Harrisburg Division

REPORTING OFFICER (signature/title)

Chief Engineer-C&S

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

R. C. Murray
Supervisory Railroad Safety Specialist
Federal Railroad Administration
Scott Plaza Two
Suite 550
Philadelphia, PA 19113

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A—Automatic
- AS—Automatic block
- ACS—Automatic cab signal
- APB—Absolute permissive block
- ATC—Automatic train control
- ATS—Automatic train stop
- CL—Color light
- CPL—Color position light
- E—Electric
- EM—Electromechanical
- EP—Electropneumatic
- FP—False proceed
- MB—Manual block
- M—Mechanical
- P—Pneumatic
- PL—Position light
- SA—Semiautomatic
- TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC				
2 INTERLOCKING <input checked="" type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL	8/7/95	Train BAL-2AH Engine 3349	CP Shocks Cab Signal at 110L Signal	Shocks Mill, PA
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Engineer on Train BAL-2AH reported cab signal upgraded from Restricting to Approach Medium with wayside home signal 110L displaying stop. Cause was found to be shorted W-10 transformer on 111 track circuit. Transformer replaced, signal system tested and placed back in service

RECEIVED
AUG 14 1995
FEDERAL RAILROAD ADMINISTRATION

2