

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

November, 1995

DATE November 20, 1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad & region or division)

Southern Pacific
Transportation Co.
Roseville Division
Black Butte Subdivision

MAIL TO

Director of Railroad Safety
Regional Administrator - 7
Federal Railroad Administration
650 Capital Mall, Suite 7007
Sacramento, CA 95814

REPORTING OFFICER (signature/title)

Engineer - Signals

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A—Automatic
- AB—Automatic block
- ACS—Automatic cab signal
- APB—Absolute permissive block
- ATC—Automatic train control
- ATS—Automatic train stop
- CL—Color light
- CPL—Color position light
- E—Electric
- EM—Electromechanical
- EP—Electropneumatic
- FP—False proceed
- MB—Manual block
- M—Mechanical
- P—Pneumatic
- PL—Position light
- SA—Semiautomatic
- TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
¹ BLOCK SYSTEMS <input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	11-16-95	Work Train 7435	Signal 4279	Klamath Falls, OR.
² INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
³ AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
⁴ OTHER (specify) Yard Limits				

NATURE AND CAUSE OF FAILURE/ CORRECTIVE ACTION TAKEN

On November 16, 1995 at approximately 3:00 PM, Engineer _____ operating work train No. 7435 traveling East, reported that while only half of his train had passed Signal 4279, he observed that Signal 4279 was YELLOW instead of RED.

Under the direction of Signal Supervisor _____ the signal system was thoroughly tested, and it was found that the 4274T and 4274AT track circuits did not slot the 4279H control. The problem was immediately corrected; the signal system was thoroughly tested and found to working as intended with no exceptions.

The signal system was returned to service on November 16, 1995 at 6:30 PM.