DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT	FO 8	(month/	year)
--------	------	---------	-------

January, 1996

DATE

January 29, 1996

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during my calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

REPORTING CARRIER (railroad & region or division)

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

CONSOLIDATED RAIL CORPORATION

R. C. Murray Supervisory Railroad Safety Specialist Federal Railroad Administration Scott Plaza Two Suite 550 Philadelphia, PA 19113

Pittsburgh Division

REPORTING OFFICER (signature/title)

Chief Engineer-C&S

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the pasic system or appliance of which it forms an essential part. E.g.: assume grounds course a block signal to indicate a faise proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

EM-Electromechanical

A-Automatic

AB-Automatic block

ACS-Autometic cab signal

APB—Absolute permissive block

ATC-Automatic train control ATS-Automatic train aton

CL-Culor light

CPL-Color position light E-Electric

EP-Electropneumatic
FP-False proceed MB-Manual block M-Mechanical

P-Pneumatic PL-Position light SA-Semiautomatic TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT	LOCATION (city and state)
BLOCK SYSTEMS X AB APB TC	1/28/96	Train HLPR 40E Engine #8226	Automatic Signal 752	Atwater, Ohio
INTERLOCKING AUTO-				
REMOTE MANUAL				
AUTOMATIC SYSTEMS ATS ATC ACS				
OTHER (specify)				<u> </u>

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Engineer on HLPR 40E reported that Automatic Signal 752 displayed a Clear Aspect with a train occupying the block. Train moves were simulated and at no time could this condition be re-created. Upon investigation, wrapped live wires were found at mile post 75 due to tree in pole line. Tree was removed, all signal components tested and inspected. A 24-hour watch was placed on Signal 752 with no exceptions taken and signal system was returned to service. A recording device was installed at Signal 752 to monitor the location. Also circuit changes are being made to eliminate the pole line involved.

SPORTATION