

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

FRA FORM F 6150-14 (6-72)

DATE

June 3, 1996

REPORTING CARRIER (initials & name or division)
Chicago, Central & Pacific Railroad

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, originally only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

US Department of Transportation
Federal Railroad Administration
Attn: Regional Director, Darrell Tisor
Federal Office Building - Room 1807
911 Walnut Street
Kansas City, MO 64106

FEDERAL RAILROAD
ADMINISTRATION

96 JUN 11 A8:49

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system component of which it forms an essential part. E.g.: assume grounds cause a failure in the track circuit. If the proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

REPORTING OFFICER (signature/initials)

Engineer, Communications
and Signals

The following abbreviations may be used in the report:

A-Automatic	EM-Electromechanical
AB-Automatic block	EP-Electropneumatic
ACS-Automatic cab signal	FP-False proceed
APB-Absolute permissive block	MB-Manual block
ATC-Automatic train control	M-Mechanical
ATS-Automatic train stop	P-Pneumatic
CL-Color light	PL-Position light
CPL-Color position light	SA-Semiautomatic
E-Electric	TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	June 1	2002	FP	West end Duncombe
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL <input type="checkbox"/> AUTOMATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE-CORRECTIVE ACTION TAKEN

Number 51's train 2002 reported clear at the west end of Duncombe with No. 50's train at MP 370.

50 reported clear east bound Lake Ole MP 369 red cab, then clear at 368.5

Cause was found to be a storm damaged pole and crossarm (hit by lightning) holding Pin 4 H wire into Pin 5 H wire at MP 368.

Maintainer cleared line and tested system.

(If more space is required, continue on reverse)