			FP-17-2-10	
DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION			REPORT FOR (month/year) 8/97	
FALSE PROCEED SIGNAL REPORT			DATE 8/22/97	
All railroads subject to Regulations of the Federal Railroad Administration shall submit a false signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.			REPORTING CARRIER (railroad & region or division)  National Railroad Passenger Corp.  30th Street Station Third Floor - South Tower Box 41 Philadelphia, PA 19104 REPORTING OFFICER (signature/title)  Assistant Chief Engineer Communications and Signals	
MAIL TO  David Myers  Administrator FRA  Scott Plaza Two - Suite 50  Philadelphia, PA 19133				
the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.  RA - Automa AB - Automa ACS - Automa APB - Absolu		tic Block EP - Electropneumatic tic Cab Signal FP - False Proceed e Permissive Block MB - Manual Block tic Train Control M - Mechanical tic Train Stop P - Pneumatic ght PL - Position Light		
TYPE OF SYSTEM  1. BLOCK SYSTEMS	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
□ AB □ APB □ TC  2. INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL	8/14/97	None	Signal 42L	North Philadelphia, PA
3. AUTOMATIC SYSTEMS  ATS ATC ACS				
4. OTHER (specify)				
NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN  At North Philadelphia Interlocking on the NEC in Philadelphia, PA. The tower operator reported a problem with the 42L signal. The CAS forces found the 42L displaying an Approach aspect with a train occurving the block. Investigation finds				

signal. The C&S forces found the 42L displaying an Approach aspect with a train occupying the block. Investigation finds cable conductor, 42LAH5 not meeting insulation resistance standards allowing foreign current to energize the 42LAH relay. The circuit was rerouted to good conductors. All appropriate tests were made along with a complete operation check observing all aspects with no exceptions found. Signal was restored to service.