			F-12-77	- C - 15
DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION			REPORT FOR (month/year) 12/97	
FALSE PROCEED SIGNAL REPORT			DATE 12/2/97	
All railroads subject to Regulations of the Federal Railroad Administration shall submit a false signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month. MAIL TO			REPORTING CARRIER (railroad & region or division) National Railroad Passenger Corp. 30th Street Station Third Floor - South Tower Box 41 Philadelphia, PA 19104 REPORTING OFFICER (signature/title)	
Mr. J. F. Me Director of Railroad Federal Railroad A Scott Plaza Two - Philadelphia, PA 1		Assistant Chief Engineer Communications and Signals		
A failure should not be counted more than one time in items 1, 2, 3 and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a falsa proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems. A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.		The following abbreviations may be used in the report. RA - Automatic EM - Electromechanical AB - Automatic Block EP - Electropneumatic ACS - Automatic Cab Signal FP - False Proceed APB - Absolute Permissive Block ATC - Automatic Train Control M - Mechanical ATS - Automatic Train Stop P - Pneumatic CL - Color Light PL - Position Light CPL - Color Position Light SA - Semiautomatic E - Electric TC - Traffic Control		
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1. BLOCK SYSTEMS X AB APB TC	12/2/97	J 01	3BSA, RELAY	Phila. Pa.
2. INTERLOCKING AUTOMATIC REMOTE MANUAL 3. AUTOMATIC SYSTEMS				
☐ ATS ☐ ATC ☐ ACS 4. OTHER (specify)				
Amtrak Train No. 653 engine no. 101 traveling west on no. 3 track passed auto signal no. 69. Auto signal 69 on no. 3 track was observed displaying "Approach" with the block occuppied. C&S forces investigating found the "3BSA" relay not wired properly. The relay was replaced. All appropriate test were made along with a complete operational check. Signal 69 was returned to service with no exceptions. Disciplinary actions have been initiated to prevent any reoccurrence.				