DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION			REPORT FOR (month/year) July 1999	
FALSE PROCEED SIGNAL REPORT			DATE July 26, 1999	
All railroads subject to Regulations of the Federal Railroad Administration shall submit a false signal report, original only, to the Federal Railroad Administration within fifteen days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.			REPORTING CARRIER (railroad & region or division)  National Railroad Passenger Corp.  30th Street Station Third Floor - South Tower Box 41	
MAIL TO Mr. David Regional Adminis Federal Railroad A International Plaz Philadelphia, PA 1		Philadelphia, PA 19104 REPORTING OFFICER (signature/title)  Chief Engineer Communications and Signals		
A failure should not be counted more than one time in items 1, 2, 3 and 4, the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.  A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.		The following abbreviations may be used in the report.  RA - Automatic		
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILE	D LOCATION (city and state)
1. BLOCK SYSTEMS  AB APB TC				
2. INTERLOCKING  AUTOMATIC REMOTE  MANUAL	7/22/99	Train #418 Eng. #4902	Charles Int. Signal 2N	Baltimore, MD
3. AUTOMATIC SYSTEMS  ☐ ATS ☐ ATC ☐ ACS				
4. OTHER (specify)				
NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN  Engineer on Train #418 reported that signal 2N at Charles Interlocking displayed approach slow aspect with 4N Signal at Paul displaying Stop aspect. Investigation revealed that a circuit design error existed in the 2NHRYPR circuit. Revision of the circuit was accomplished by breaking the 2NHRYPR circuit through the front contact of the 66RWCR. Circuitry was changed, tests completed and signal system returned to service.				