

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to regulation by the Federal Railroad Administration shall submit a false proceed signal report, signed only, to the Federal Railroad Administration no later than 10 days after a false proceed occurs. If no false proceed occurs during any calendar month, a report bearing "No False" shall be filed within ten days after the end of the month.

Copies of this form will be furnished, upon request, to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Tom Marks
Signal & Train Control Specialist
111 N. Canal St., Suite 635
Chicago, IL 60606

DATE	2/7/2000
REPORTING OFFICER (Signature)	
Canadian National Railroad	

Supervisor of Signals

A failure should not be considered more than one error in systems 1, 2, 3, 4, and 5. The failure should be classified under the system or condition of which it forms no integral part. E.g. - assume primary error - a block designed to indicate a false proceed condition corresponding indication of a non-block system on some train commanding the power. Such failures should be included in item 1. Work Spans.

A false proceed failure is a failure of a system. Errors as applicable to control or function of selected units require no less reexamination than indicated.

The following abbreviations may be used in the report:

AS	Automatic
ATC	Automatic block
ATS	Automatic and manual
ATP	Automatic permissive block
ATC	Automatic train control
ATP	Automatic train protection
CL	Color light
CPL	Color permissive light
E	Electric
DN	Downward movement
GP	Grade permissive
PP	Power protected
SP	Segmental
TC	Manual
TC	Permissive
TC	Prohibited
TC	Train control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS				
<input type="checkbox"/> AS <input type="checkbox"/> APM <input checked="" type="checkbox"/> TC				
2 INTERLOCKING				
<input checked="" type="checkbox"/> DEMOTE <input type="checkbox"/>				
3 AUTOMATIC SYSTEMS				
<input type="checkbox"/> ATP <input type="checkbox"/> ATC <input checked="" type="checkbox"/> ACS				
4 OTHER (specify)				

NOTING AND CAUSES OF FAILURE, CORRECTIVE ACTION TAKEN

At 05:30 on 2/9/00 a CN train approaching the interlocking at Wellsboro Indiana, South Bend Subdivision MP71.1 reported that westward home signal WB2w had a clear aspect when the crew knew that the signal should have been a approach. The investigation of the signal system found that the root cause of the false proceed was intermittent foreign voltage on the "H" control wire. The foreign voltage was traced back to MP70.9 where a obsolete wire had broken and wrapped itself around the control wires "H" and "D" causing a short on the line. The wrapped wire was removed and all circuit tested. Remedial action, all control wires will be inspected monthly.

Note 1: Locomotive number unknown, train crew notified FRA.