

DATE

5-18-01

REPORTING CARRIER (Railroad &amp; section or division)

Delaware and Hudson Railway Co

Trains subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration five days after a false proceed occurs. If no false proceed occurs during any month, a report showing "No Failure" must be filed within ten days after the month.

1. Of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

TO

Federal Railroad Administration  
Office Of Safety  
Washington D.C. 20590

REPORTING OFFICER (Signature/Title)

KR Dodge  
S+CS

There should not be created more than one line item Item 1, 2, 3, and 4 if the failure is classified under the basic system or appliance of which it forms an essential part. Each assume grounds cover a block signal to indicate a false proceed or corresponding indications of a cab signal system on each train approaching that, such failures should be included in Item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or show as intended which results in less restriction than intended.

The following abbreviations may be used in the report:

A-Automatic	EM-Electromechanical
AB-Automatic block	EP-Electropneumatic
ACS-Automatic cab signal	FP-False proceed
APB-Absolute permissive block	MB-Manual block
ATO-Automatic train control	M-Mechanical
ATS-Automatic train stop	P-Pneumatic
CL-Color light	PL-Position light
CPL-Color position light	SA-Semiautomatic
E-Electric	TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
LOCK SYSTEMS			Signal	
<input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	5-9-01	S88.6A		MP 588.6 AFTON NY
PERLOCKING				
<input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
AUTOMATIC SYSTEMS				
<input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
OTHER (specify)				

## CAUSE AND SOURCE OF FAILURE/CORRECTIVE ACTION TAKEN

SV2 was stopped at CPFS90 on The controlled Siding with Train # 550-08 stopped behind them at Signal 588.6 waiting for a North bound Train. CPFS90 was cleared North on The main track. Train 550-08 had reported that Signal 588.6A (Southward approach to CPFS90 on the main TK) was going Red to Green. SV2 reported CPFS90 staying at stop. The cause was over hanging tree limbs at mp 589.2 wrapping line wires #3 and #4 on the middle cross arm. Pin #3 is 29 LAHD and Pin #4 is 116.2 CHD. This condition had Signal 588.6A going Red to Green. After the line wires were unwrapped to clear the problem we had then resimulated the problem by putting the wires back together. The signals were returned to service at 13:14 hrs on 5-11-01.