

This form will be furnished upon request to the Department of Transportation.  
Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

6-8-01

REPORTING CARRIER Railroad & section or division

Delaware and Hudson Railway Co

Federal Railroad Administration  
Office Of Safety  
Washington D.C. 20590

REPORTING OFFICER (Signature/Initials)

KR Dodge SCHS

We should not be created more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. This assumes grounds cover a block signal to indicate a false proceed & corresponding indications of a cab signal system on each train approaching that block. Such failures should be included in item 1, Block Systems.

A proceed failure is a failure of a system, device or appliance to indicate or to act in accordance with its intended function which results in less restriction than indicated.

The following abbreviations may be used in the report:

A-Automatic	EM-Electromechanical
AB-Automatic block	EP-Electropneumatic
ACS-Automatic cab signal	FP-False proceed
APB-Absolute permissive block	MB-Manual block
ATO-Automatic train control	M-Mechanical
ATC-Automatic train control	P-Pneumatic
CL-Color light	PL-Position light
CPL-Color position light	SA-Semi-automatic
E-Electric	TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
CK SYSTEMS				
<input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	6-501	Train # 268	Signal 2.2 -	Menands N.Y
ERLOCKING				
<input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
OMATIC SYSTEMS				
<input checked="" type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
IER (specify)				

REASONS AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Train # 268 had reported that the Southbound Signal at CP04 went from Stop to Clear (for about 2 sec) and back to Stop again. The Work Train (2 Light engines) was going south ahead of Train # 268. When the work train went past Signal 2.2, it caused the timing between the Electro Code Circuits south of the signal and the DC battery circuits north of the signal to allow this condition to exist. We have corrected this timing problem and retested the signals.