

Records subject to regulations of the Federal Railroad Administration shall submit proceed signal report, original only, to the Federal Railroad Administration five days after a false proceed occurs. If no false proceed occurs during any month, a report showing "No Failures" must be filed within ten days after the end of the month.

1 Railroad Administration, Office of Safety, Washington, D.C. 20590

Federal Railroad Administration
Office Of Safety
Washington D.C. 20590

6-8-01
REPORTING CARRIER Railroad & section or division

Delaware and Hudson Railway Co

REPORTING OFFICER (Signature/Title)

KR Dodge SC+S

It should not be counted more than one time in Item 1, 2, 3, and 4; the failure be classified under the basic system or appliance of which it forms an essential part. E.g. assume ground current a block signal to indicate a false proceed & corresponding indications of a cab signal system on each train approaching that, such failures should be included in item 1, Block Systems.

A proceed failure is a failure of a system, device or appliance to indicate or to act as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic	EM-Electromechanical
AB-Automatic block	EP-Electropneumatic
ACS-Automatic cab signal	FP-False proceed
APB-Absolute permissive block	MB-Manned block
ATO-Automatic train control	M-Mechanical
ATC-Automatic train stop	P-Pneumatic
CL-Color light	PL-Position light
CPL-Color position light	SA-Semiautomatic
E-Electric	TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
CK SYSTEMS				
AB <input type="checkbox"/> APB <input type="checkbox"/> TC				
ERLOCKING <input type="checkbox"/>		Train # SCR	Eastward Home Signal CPF467	Mechanicville, N.Y.
REMOTE <input checked="" type="checkbox"/> MANUAL				
OMATIC SYSTEMS				
ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
IER (specify)				

REASON AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

The Springfield Terminal Dispatcher had Called Train #SCR To See why They had proceeded Through The control Point at CPF467. The Dispatcher did Not have a signal Cleared at This Location. At this time Train SCR had reported That they had an approach Signal at CPF467. The Signal at CPF467 was out of Focus due to a broken bracket that hold the Signal housing. With the Signal out of Focus and the position of the Sun Shining on the Signal had Caused the Signal to appear yellow. The Signal bracket was replaced and The Signal was refocused. The Signal was rechecked under the same condition and the Signal displayed the proper aspects.

5