NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

ATC

MATIC

MANUAL

ACS

9/5/01

On September 5, 2001, at approximately 11:00 AM, engine 30 reported an APPROACH/MEDIUM aspect on signal 188 and a STOP aspect on signal 150. Upon arrival, had the Union Railroad TMD (Dispatcher) request a signal on 188 and an APPROACH/MEDIUM aspect displayed (yellow over green). The proper aspect should have been an APPROACH (yellow). Signal 188 was taken out of service.

Plant grounds were checked and found okay. Voltages were checked between case 27 and case 186. Cable 27-186A was meggered and had several bad conductors in the 19 conductor cable. This cable was last meggered on 12/1/98. A new 9 conductor cable was run and circuits were moved to the new cable. The new cable was meggered and all signal aspects were operational checked. Signal 188 was

Engine 30

188 Signal

J Tower Interlocking, Duquesne,

REMOTE

3 AUTOMATIC SYSTEMS ATS

4 OTHER (apocify)