DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

REPORT FOR (month/year)

омв No. 2130-0006

FALSE	PROCEED	SIGNAL	REPORT
-------	---------	--------	--------

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

US Department of Transportation Federal Railroad Administration 2 International, Plaza, Suite 550 Lester, PA 19113

The River Line New Tersey

REPORTING OFFICER (signature/title)

Signal Supervisor

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the nasic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic

AB-Automatic block

ACS-Autometic cab signal APS-Absolute permissive block

ATC-Automatic train control

ATS-Automatic train stop

CL-Culor light

CPL-Color position light E-Electric

EM-Electromechenical EP-Electropneumatic FP-False proceed

MB-Manual block M-Mechanical

P-Pneumatic PL-Position light SA-Semiautomatic

TC-Treffic control TYPE OF SYSTEM LOCOMOTIVE DATE DEVICE THAT NUMBER FAILED LOCATION (city and atale) BLOCK SYSTEMS TC 3/20/04 LRV 3508 X REMOTE Burlington, NJ 4 OTHER (apacify) NATURE AND CAUSE OF FAILURE CORRECTIVE ACTION TAKEN

See Attached

April 15, 2004

Date of Incident: 3/20/04

Location: CP 175, Burlington, NJ

Train # 247 (equipment LRV # 3508) was tripped by the 2N-2 train stop while heading south through CP175 interlocking. The VHLC download revealed the train was tripped because track circuit 1AT picked up while the train was occupying the circuit. The circuit picked up for a duration 8 seconds (1 second over the loss of shunt timer) due to poor shunting. At no time was there a more favorable aspect displayed than stop.

Immediate action was taken in the form of lowering the track circuit relay current from 230 milliamps to 190 milliamps. A recorder was setup to monitor shunting and additional rail scrubbing has been scheduled for this area.

Regards,

Signal Supervisor Bombardier Transportation

APR 19 2004