DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
City Center Square, Suite 1130
1100 Main Street
Kansas City, MO 64105-2112

REPORT FOR (month/year)

November 1995

DATE

December 8, 1995

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

Los Angeles Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic
AB = Automatic block
ACS = Automatic Cab Signal
APB = Absolute permissive block

ATC = Automatic train control ATS = Automatic train stop

CL = Color light
CPL = Color position light
E = Electric

EM = Electromechanical

EP = Electropneumatic FP = False proceed MB = Manual block M = Mechanical P -= Pneumatic

PL = Position light SA = Semiautomatic TC = Traffic Control

• *			L LIV	edic 10 Haine conde
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS □ AB □ APB ☑ TC	11/28/95	NPST-26	None	Orinosa, Utah
2 INTERLOCKING				
3 AUTOMATIC SYSTEMS ATS ATC ACS				
4 OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On November 28, 1995, at 13:45 (CDT) on the Elko Subdivision, westbound train NPST-26 had a green aspect at Signal No. 830.1, a flashing yellow aspect at Signal 827.7 and a diverging red over lunar aspect at Signal CP F826.

An investigation revealed the signal case at MP 827.7 had been run into by a vehicle and upset relays RLPR, 180CTR, and DRAR which had to be replaced.

The signal system was restored to proper operation, and all applicable tests were performed.