

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

Tom Maske
Federal Railroad Administration
111 N. Canal Street
Suite 655
Chicago, IL 60606

REPORT FOR (month/year)

July 2000

DATE

7/21/00

REPORTING CARRIER (railroad & region or division)

Wisconsin Central Ltd
3000 Minnesota Avenue
Stevens Point, WI 54481

REPORTING OFFICER (signature/title)

Engineer Signals

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point. such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A—Automatic
- AB—Automatic block
- ACS—Automatic cab signal
- APB—Absolute permissive block
- ATC—Automatic train control
- ATS—Automatic train stop
- CL—Color light
- CPL—Color position light
- E—Electric
- EM—Electromechanical
- EP—Electropneumatic
- FP—False proceed
- MB—Manual block
- M—Mechanical
- P—Pneumatic
- PL—Position light
- SA—Semiautomatic
- TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	7/20/00	L017-20 WC 6620	Signal 2516	Stevens Point, Wisconsin
2 INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL <input type="checkbox"/> AUTO-MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE / CORRECTIVE ACTION TAKEN

- * As NB Train L017 passed approach Signal 2517, Engineer looked back and observed SB Signal 2516 at "approach" while the 52 car train was still on the circuit.
- * No defects found. Unable to replicate after numerous simulations. Signal returned to service after testing complete.

(If more space is required, continue on reverse)