



**IronWood
Technologies**
Railroad Accident Reconstruction

Federal Railroad Administration
False Proceed Signal Database

January 1, 1995 through May 3, 2004

All Reports - Southern California Regional Rail Authority

Report #	Date	Reporting Carrier	Block System	Interlocking	Auto. Systems	Loco or Train No.	Device that Failed	Location	Collision or Derailment?
597	4/3/1998	SCRA	CTC			Eng. #876	EC-4H/VHLCprog.	Glendale, CA	N
Cause									
Human Error - Signal Circuit Design Error, Inadequate Service-Testing									
Added "Joint Hop Logic" to Executive Software [see printed report]									

No. of Reports Shown in this Listing: 1